

February 3, 2020

Continued temperature pull down. Completed painting at satellite offices and demising walls. Continued installing racking. Began final clean. Tested fire protection systems. Completed interior glass installation. Completed satellite office toilet accessories and partitions.

